

Tradewater Lower Green Summer 2014 Results

COC_ID	Site #	Historic	Stream Name	Location	County	Sample Date	Sample Time	Associate LN	General Comments	Analysis Date	Analysis Time	E. coli	Analysis Date	Analysis time	Lab Turbidity	Flag
3314	2096	T11	Greasy Creek	At BSA camp on Tucker Schoolhouse Rd	Hopkins	7/12/2014	0900	Norton	Creek was dry so no sample could be taken							
3941	2097		YAA	Stream by Youth Athletic Association W. Center Street Madisonville	Hopkins	7/12/2014		Janssen	Thin oily like film on water near banks. Upstream from test site(20 yards ?) is a dam like barrier where tree trunks and branches are across stream. Debris, flourescent bulbs instream at site	7/12/2014	1442	<10	7/12/2014	1826	3.02	sampler did not record time they collected sample on coc.
3110	2125	T41	North Fork Panther Creek	US 231 near Masonville	Daviess	7/12/2014	0845	Connor		7/12/2014	1522	644	7/12/2014	1806	6.24	
3436	2128	T44	South Fork Panther Creek	KY 298 east of Sutherland.	Daviess	7/12/2014	1005	Rieger	Sample taken by bucket drop from bridge. Tested DO twice for accuracy	7/12/2014	1558	52	7/12/2014	1806	23.6	
1988	2178	T95	South Fork Panther Creek	231 bridge	Daviess	7/12/2014	0930	Rieger	Slight oil film	7/12/2014	1522	52	7/12/2014	1806	13.1	
2806	2209	T150	East Fork Knoblick Creek	Sentinel upstream Mulligan Rd bridge	Daviess	7/12/2014	0804	Toepfer		7/12/2014	1442	10	7/12/2014	1807	2.01	
2808	2224	T165	Cypress Creek	Sentinel Hwy 1589 bridge	McLean	7/12/2014	0755	Rector	Didn't do Ph test, my cup was stuck on the solution. Need new Ph solution. 41 miles 1hr 40mins	7/12/2014	1442	213	7/12/2014	1807	8.07	
2807	2270	T280	Piney Creek	Cool Springs Rd	Crittenden	7/12/2014	0910	O'Hara	Some junk in creek- Tires, TV, Barbell weights; 78 miles 3 hours	7/12/2014	1522	52	7/12/2014	1809	14.6	
2809	2286	T308	Pond Drain	Sentinel Pond Drain Rd Bridge just west of semiway off KY 81	McLean	7/12/2014	0825	Rector	Didn't do Ph test. My cup was stuck. Need new Ph solution	7/12/2014	1442	135	7/12/2014	1809	25.8	
3305	2299	T330	Barnett Creek	Bridge on Hwy 136 west of Heflin	Ohio	7/12/2014	0849	Neal		7/12/2014	1522	146	7/12/2014	1814	5.79	
3119	2324	T379	Persimmon Ditch	North side of Owensboro at Hwy 331 bridge	Daviess	7/12/2014	0915	Flachskam		7/12/2014	1522	238	7/12/2014	1814	19.1	
3112	2329	T390	Scherm Ditch	Scherm Rd and Barron Dr bridge	Daviess	7/12/2014	0950	Flachskam	3 feet of shoreline contained algae which contaminated sample.	7/12/2014	1558	31	7/12/2014	1815	52.3	
3023	2353	T491	Burnett Fork	South of Philpot on HWY 142	Daviess	7/12/2014	0945	Mayton		7/12/2014	1522	331	7/12/2014	1815	24.7	
3311	2356	T503	Pup Creek	Bridge on 1389 near Spice Knob. OHIO RIVER ACTION	Daviess	7/12/2014	0815	Barker	Creek was running very slowly	7/12/2014	1442	295	7/12/2014	1815	6.36	
3113	2357	T504	Yellow Creek	Bridge at US 60 OHIO RIVER ACTION	Daviess	7/12/2014	0930	Connor		7/12/2014	1522	399	7/12/2014	1816	19.5	
2636	2389	T583	Twomile Creek	KY 140 east of Utica	Daviess	7/12/2014	0815	Rieger	No floating debris	7/12/2014	1442	1565	7/12/2014	1817	43.7	
3114	2397	T605	Canoe Creek	Off Lovers Lane bridge		7/12/2014	0730	Comer II		7/12/2014	1442	373	7/12/2014	1817	33.6	
3115	2398	T606	South Fork Canoe Creek	hwy 425 bridge	Henderson	7/12/2014	0755	Comer II	Even though the flow rate was low, there was less turbidity than we recall ever before & spotted a turtle swimming in the creek	7/12/2014	1442	243	7/12/2014	1817	33.1	
3116	3008		Unnamed Tributary	just off KY 175 - trib to Thompson Creek	Muhlenberg	7/12/2014	0800	Galyen	Sampling error 3008 E.Coli, no sample submitted. 50 miles	7/12/2014			7/12/2014	1818	7.24	
3117	3009		Unnamed Tributary	just off US 62 - trib to Thompson Creek	Muhlenberg	7/12/2014	0750	Galyen	Sampling error 3009 E.Coli, no sample submitted. 50 miles	7/12/2014			7/12/2014	1822	7.92	

